Join group: T.me/NOUNSTUDENTSFORUM CLICK TO DOWNLOAD MORE TMA PQ

reference to the observer. clockwise [ESM421] is a pre-field work and measurement phase Reconnaissance survey [ESM421] with the compass involves taking the bearing along a series of connecting straight lines and in the same time measuring the distances with the tape. Traversing [ESM421] The reference North may be true or ____ magnetic [ESM421] _____is an optical instrument used to take offsets at right angles from the chain lines. Optical Squares [ESM421] _____ survey depicts the hills, valleys, mountains, rives, and man made features (roads, houses, settlements on the surface of the earth. Topographic [ESM421] survey is suitable on an open and well level piece of land with nonsimple details; where large scale plans/maps are need and, where the area is small in extent. Chain [ESM421] In_____horizontal angular measurements are made using magnetic compass with the linear measurements made using the chain or jape. Compass Surveyre [ESM421] _____ surveying is survey in a small extent hence the earth¢â,¬â,,¢s surface is assumed to be a plane and the curvature of the earth is ignored. Plane [ESM421] The act of establishing the elevation of points on or below the surface of the earth is called distraction errors

Whatsapp: 08089722160 or click here for TMA assistance